

**e-RA - Atualizado em: 15/04/2024**

Número BAC	Cotação e-RA	Número da Peça	Nome do Item	Classe	Fabricante	Qtd	Valor Máximo Unit.	Fechamento da Fase Inicial de Propostas
SPR038011T9	46/2024	FED519-119-1CCW	BLOWER WHEEL - TBO ITEM FROM PN: EM657-3 & IW. EXT DIAM: 142,5MM / 5 5/8" OR CLOSE WIDTH: 79MM / 3 1/8" OR CLOSE BORE DIAM: 1/2" STEEL CCW - COUNTER CLOCKWISE DOUBLE INLET	1660	54395	5	US\$ 1072.83	25/04/2024 11:00:00 GMT-3 (-03:00)
GLR029003C1	49/2024		FLYSMART WITH AIRBUS FOR I-PAD - GATEWAY ADMINISTRATION LOCATION: DISTANT LEARNING COURSE CODE: XG04I2			2	US\$ 1656.60	16/04/2024 11:00:00 GMT-3 (-03:00)
GLR003004C4	50/2024	MS9952-27	WASHER, RECESSED - WASHER, RECESSED - IPC 72-59-00-01, FIG. 01, PAGE 01, ITEM 160.	5310	63005	4	US\$ 144.52	23/04/2024 11:00:00 GMT-3 (-03:00)
GLR003002GG	51/2024	121622-001	CIRCUIT CARD ASSEMBLY - CIRCUIT CARD ASSEMBLY - NSN: 5998 014076630 - WITH FRESH FAA FORM 8130-3	5998	02294	10	US\$ 2742.46	23/04/2024 11:00:00 GMT-3 (-03:00)
GLQ307015P3	52/2024	585500	SYNCHROPHASER - NAVAIR 01-XPAA-4-8 F0089-00 ITEM 27	1610	73030	1	US\$ 23141.00	23/04/2024 11:00:00 GMT-3 (-03:00)
SPRR06802H7	53/2024	29333306	REPAIR - THE ACCESSORY PN: 29481301, SN: 7309 (CADU), SHOWS THE FOLLOWING FAULT DURING THE CALIBRATION PROCESS: "ERROR 32454: CADU STILL SETTING UP THE DAU". MAINTENANCE ACTIONS PROVIDED FOR IN TM 1-6625-736-13&P WERE CARRIED OUT, BUT WITHOUT SUCCESS. IT SHOULD BE INFORMED THAT A SIMILAR CALIBRATION PROCEDURE WAS CARRIED OUT WITH ANOTHER CADU UNIT FROM ANOTHER RADS KIT, IN WHICH THIS ERROR WAS NOT OBSERVED. *** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS: 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE # 2) FIXED EVALUATION FEE. 3) SERVICE OFFERED WARRANTY. 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. *** IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DESCLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12). ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 45 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS. THE TEARDOWN REPORT MUST HAVE: 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES. 2 - ESTIMATED DELIVERY DATE. 3 - SERVICE WARRANTY. 4 - FIXE EVALUATION FEE. ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL. ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. ATTENTION: UNITS DEEMED BER/BPR RETURNING AS IS, A TEARDOWN REPORT MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. IN THIS CASE, THE UNIT MUST BE RETURNED IN THE SAME CONDITION AS RECEIVED BY THE CONTRACTED PARTY (ASSEMBLED).	5841	35012	1	US\$ 20095.64	23/04/2024 11:00:00 GMT-3 (-03:00)
SPRR07204H7	54/2024	ECF40002	REPAIR - EQUIPMENT SENT TO LRC-SP WITH A LEAK FAILURE IN THE VALVE, AS DESCRIBED ON THE YELLOW SUPPLY LABEL. WHEN ATTEMPTING TO START THE TESTS THE EQUIPMENT DID NOT TURN ON. *** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS: 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE # 2) FIXED EVALUATION FEE. 3) SERVICE OFFERED WARRANTY. 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. *** IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DESCLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12). ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 45 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS. THE TEARDOWN REPORT MUST HAVE: 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES. 2 - ESTIMATED DELIVERY DATE. 3 - SERVICE WARRANTY. 4 - FIXE EVALUATION FEE. ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL. ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. ATTENTION: UNITS DEEMED BER/BPR RETURNING AS IS, A TEARDOWN REPORT MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. IN THIS CASE, THE UNIT MUST BE RETURNED IN THE SAME CONDITION AS RECEIVED BY THE CONTRACTED PARTY (ASSEMBLED).	4920	20722	1	US\$ 7927.14	23/04/2024 11:00:00 GMT-3 (-03:00)

SPRR07103H7	54/2024	29333306	REPAIR - THE EQUIPMENT PRESENTS INTERMITTENT FAILURE ON THE KEYPAD. *** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS: 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE # 2) FIXED EVALUATION FEE. 3) SERVICE OFFERED WARRANTY. 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. *** IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DESCLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12). ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 45 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS. THE TEARDOWN REPORT MUST HAVE: 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES. 2 - ESTIMATED DELIVERY DATE. 3 - SERVICE WARRANTY. 4 - FIXE EVALUATION FEE. ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL. ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. ATTENTION: UNITS DEEMED BER/BPR RETURNING AS IS, A TEARDOWN REPORT MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. IN THIS CASE, THE UNIT MUST BE RETURNED IN THE SAME CONDITION AS RECEIVED BY THE CONTRACTED PARTY (ASSEMBLED).	5841	35012	1	US\$ 19530.65	23/04/2024 11:00:00 GMT-3 (-03:00)
SPRR07102H7	54/2024	SK1010	REPAIR - EMP HAS A MALFUNCTION IN THE DIFFERENTIAL PRESSURE VALVE, IT IS NOT POSSIBLE TO CARRY OUT THE CALIBRATION, IN ADDITION TO THE DISPLAY IS LOOSE. *** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS: 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE # 2) FIXED EVALUATION FEE. 3) SERVICE OFFERED WARRANTY. 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. *** IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DESCLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12) ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 45 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS. THE TEARDOWN REPORT MUST HAVE: 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES. 2 - ESTIMATED DELIVERY DATE. 3 - SERVICE WARRANTY. 4 - FIXE EVALUATION FEE. ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL. ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. ATTENTION: UNITS DEEMED BER/BPR RETURNING AS IS, A TEARDOWN REPORT MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. IN THIS CASE, THE UNIT MUST BE RETURNED IN THE SAME CONDITION AS RECEIVED BY THE CONTRACTED PARTY (ASSEMBLED).	4920	51826	1	US\$ 4018.12	23/04/2024 11:00:00 GMT-3 (-03:00)
SPRR07101H7	54/2024	05-0330-07	REPAIR - EQUIPMENT SENT TO LRC-SP DUE TO FAILURE IN THE "BIAS ADJUST" TEST, STEP 7, ACCORDING TO PROCEDURES ADOPTED BY THE OPERATOR. *** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS: 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE # 2) FIXED EVALUATION FEE. 3) SERVICE OFFERED WARRANTY. 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. *** IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DESCLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12). ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 45 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS. THE TEARDOWN REPORT MUST HAVE: 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES. 2 - ESTIMATED DELIVERY DATE. 3 - SERVICE WARRANTY. 4 - FIXE EVALUATION FEE. ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL. ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. ATTENTION: UNITS DEEMED BER/BPR RETURNING AS IS, A TEARDOWN REPORT MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT. IN THIS CASE, THE UNIT MUST BE RETURNED IN THE SAME CONDITION AS RECEIVED BY THE CONTRACTED PARTY (ASSEMBLED).	6625	07PR7	1	US\$ 34322.34	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072004T1	55/2024	PWC50618	HOLDER -	4920	00198	2	US\$ 2184.69	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072012T1	55/2024	PWC30458	TOOL LOCKING - NSN 5120-001104541	5120	00198	2	US\$ 908.99	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073008T2	56/2024	PWC50931	TACHOMETER,ELECTRON - NSN: 6680-01-617-0620	6680	61858	3	US\$ 8431.36	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072022H2	56/2024	505455-1	ARMATURE,GENERATOR - NSN 2925-145587095 - IW N151554-2 - NHA: 524-031	2925	F0296	1	US\$ 7144.09	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR074013H2	56/2024	V922005K	RING, RETAINING - NHA: 524-031	1560	F0296	2	US\$ 62.63	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072020H2	56/2024	410997	BEARING,BALL,ANNULAR - NSN 3110-14-466-5960	3110	F0296	1	US\$ 366.97	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072019H2	56/2024	46100	WASHER,KEY - NSN 5310-14-248-1544 - NHA: 524-031	5310	F0296	4	US\$ 3.43	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR074015H2	56/2024	P722698	NUT,PLAIN,HEXAGON - NSN: 5310-14-557-5219 - NHA: 524-031	5310	F0296	3	US\$ 96.32	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR074014H2	56/2024	90006604	WASHER,LOCK - NSN: 5310-14-580-0042	5310	F0296	3	US\$ 50.00	23/04/2024 11:00:00 GMT-3 (-03:00)

SPRP07306T2	57/2024		PN.: 3077076 - MAINTENANCE COLLECTION (MAINTENANCE MANUAL, PARTS CATALOG, GROUND-BASED SOFTWARE, ALL BULLETINS - PT6A-68C), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			10	US\$ 356.86	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07302A7	57/2024		PN.: 3077123 - MAINTENANCE AND OVERHAUL COLLECTION (MAINTENANCE COLLECTION PLUS OVERHAUL MANUAL: PT6A-34/34AG/34B/35/36/114/114A/135/135A), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			5	US\$ 8227.80	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07301A7	57/2024		PN.: 3077056 - MAINTENANCE COLLECTION (MAINTENANCE MANUAL, PARTS CATALOG, ALL BULLETINS - PT6A-34/34AG/34B/36), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			10	US\$ 288.26	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07305T1	57/2024		PN.: 3077122 - MAINTENANCE AND OVERHAUL COLLECTION (MAINTENANCE COLLECTION PLUS OVERHAUL MANUAL - PT6A-25C), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			5	US\$ 8227.80	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07307U8	57/2024		PN.: 3077052 - MAINTENANCE COLLECTION (MAINTENANCE MANUAL, PARTS CATALOG, ALL BULLETINS - PT6A-114/114A/135/135A), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			15	US\$ 247.08	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07304H3	57/2024		PN.: 3077030 - MAINTENANCE COLLECTION (MAINTENANCE MANUAL, DIAGNOSTIC TOOL, PARTS CATALOG, GBS, ALL BULLETINS - PW206B/206B2/206B3), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			5	US\$ 569.80	16/04/2024 11:00:00 GMT-3 (-03:00)
SPRP07303A7	57/2024		PN.: 3011100 - COMPONENT MAINTENANCE MANUAL COLLECTION (ENGINE ACCESSORIES: PT6A-25), MEDIA TYPE ONLINE, ENGLISH, SUBSCRIPTION ONE (1) YEAR.			5	US\$ 20695.80	16/04/2024 11:00:00 GMT-3 (-03:00)
SPR065015H2	58/2024	P711933-1	BUSHING	3040	F0210	1	US\$ 452.61	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR065003H2	58/2024	Z31219	FUSEHOLDER,EXTRACTOR POST - FUSEHOLDER,EXTRACTOR POST - ALTERNATE 231219N	5920	F0240	25	US\$ 13.92	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR065010H2	58/2024	P600653	DISQUE, DE TRANSMISS - DISQUE, DE TRANSMISS - NSN 3040-14-458-6255	3010	F0296	1	US\$ 446.27	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR066004H2	58/2024	406021	STUD,SHOULDERED ANDS ...	5307	F0296	2	US\$ 100.95	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR065016H2	58/2024	601145	COVER - TERMINAL BOAR - NSN 5940-14-233-9451	5940	F0296	1	US\$ 411.55	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR065009H2	58/2024	410964	BEARING,BALL,ANNULAR - BEARING,BALL,ANNULAR - IW B320050L - NSN 3110-14-568-3750	3110	F0296	1	US\$ 208.91	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR065012H2	58/2024	P723856	SCREW,MACHINE - SCREW,MACHINE - NSN 5305-22-617-1140	5305	S8593	8	US\$ 196.42	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR022001F9	59/2024	COM00561	ADAPTOR AND FIXTURE MBEU57657	1560	A166N	1	US\$ 9594.94	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026006F9	59/2024	P38987	GAUGE, PLUG, BEARING BUSHES - PLUG GAUGE GO/NO GO. 0.187" / 0	1560	A166N	3	US\$ 299.96	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR029002F9	59/2024	MBEU114959	SEAL, O-RING - O RING SEAL	5330	A166N	40	US\$ 11.66	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR029003F9	59/2024	MBEU124025	LINE ASSEMBLY, LOWER ARM RESTRAINT -	5310	A166N	20	US\$ 453.92	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR025003F9	59/2024	MBEU82411	BLANKING PLUG - CAP INLET, CONNECTOR	5340	A166N	4	US\$ 141.81	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026005F9	59/2024	P37819	CLECO HEAD OE - 3/4 IN. - SPANNER HD 819008 OE3/4	1680	A166N	1	US\$ 126.59	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR074157F9	59/2024	MBEU3973DP	TOOL,SPRING - TOOL ASSY SPECIAL	5120	U1604	2	US\$ 3098.66	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024005F9	59/2024	MBEU56378	SPANNER,OE,13/16IN	5120	U1604	3	US\$ 291.27	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024001F9	59/2024	MBEU170503	TOOL, RIGGING LINE LINK SEPARATOR - SEPARATOR ASSY	1680	U1604	4	US\$ 11301.11	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024010F9	59/2024	MBEU57832	SCREWDRIVER SET,TORQUE -	5120	U1604	7	US\$ 1791.24	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR072002F9	59/2024	MBEU192164	LEAD SHOT BAGS - LEAD SHOT BAGS	1670	U1604	6	US\$ 551.99	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR025004F9	59/2024	MBEU82755	PACKING PLATE, LEFT SIDE - BLOCK ASSY LEFT - PARACHUTE PAC	1560	U1604	1	US\$ 3298.94	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR072003F9	59/2024	MBEU59604	ADAPTER, TORQUE - ADAPTER,TORQUE	5120	U1604	6	US\$ 1418.41	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024017F9	59/2024	MBEU58930	ROLLER ASSEMBLY,LOAD - LOAD ROLLER ASSY HPRU	4920	U1604	3	US\$ 7514.42	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026003F9	59/2024	MBJ25046-1	TOOL,ROLLING EYELET - ROLLING TOOL	5180	U1604	4	US\$ 6325.89	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR071004F9	59/2024	MBEU115240	SAFETY PIN AND STREAMER ASSEMBLY - SAFETY PIN AND STREAMER ASSEMBLY	1680	U1604	6	US\$ 265.50	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR065002F9	59/2024	MBEU57796	WRENCH,SPANNER - SCREWDRIVER SPECIAL, HAWKER NUTS	5120	U1604	2	US\$ 1817.12	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR029001F9	59/2024	MBEU76555	CHATTLON, PUSH/PULL GAUGE 100 LGF -	6685	U1604	3	US\$ 2940.74	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR023001F9	59/2024	MBEU115304	ADAPTER, BLADDER LEAK TEST - ADAPTOR ASSY TESTING	4920	U1604	6	US\$ 1474.27	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR073002F9	59/2024	P32869	GREASE ASG 7 - GREASE MIL-PRF-23827C TYP II AS	9150	U1604	6	US\$ 36.42	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024006F9	59/2024	MBEU57044	SPANNER, FN 1/2 IN. AF	5120	U1604	3	US\$ 360.07	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024003F9	59/2024	MBEU4709DP	TOOL ASSY BIT	4920	U1604	4	US\$ 2028.97	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024008F9	59/2024	MBEU57047	RESETTING TOOL ASSEMBLY - TOOL ASSY RESETTING	5120	U1604	9	US\$ 989.80	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024002F9	59/2024	MBEU34491	WRENCH,SPANNER - SCREWDRIVER SPECIAL	5120	U1604	6	US\$ 1678.99	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024004F9	59/2024	MBEU5113DP	SCREWDRIVER - SCREWDRIVER ASSY	1680	U1604	6	US\$ 1944.53	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR025002F9	59/2024	MBEU74320	ADAPTER,CHECK -	4220	U1604	4	US\$ 589.72	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026001F9	59/2024	MBEU82775	PLATE, PRESSURE, FRONT - PLATE ASSY PRESSURE FRONT	1680	U1604	1	US\$ 3298.94	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR025005F9	59/2024	MBEU82770	SUPPORT PLATE - PLATE SUPPORT PARA CONT	5130	U1604	4	US\$ 533.95	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR071001F9	59/2024	MBEU62796	STRAP,WEBBING - LINE ASSY LEG REST 54IN	1680	U1604	354	US\$ 591.16	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024014F9	59/2024	MBEU57835	SOCKET,SOCKET WRENCH -	5120	U1604	3	US\$ 1406.87	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026004F9	59/2024	P37330	WRENCH,TORQUE - 0 WRENCH TORQUE 869765	5120	U1604	3	US\$ 1058.07	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR073001F9	59/2024	MBEU90475	NUT SUB-ASSEMBLY - NUT SUB-ASSEMBLY, RETAINING	1680	U1604	10	US\$ 444.82	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR026002F9	59/2024	MBJ16537	FIXTURE,AIRCRAFT MAINTENANCE - 7 FIXTURE ASSY T/LATCH PLNG	4920	U1604	3	US\$ 11096.28	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024018F9	59/2024	MBEU59027	TOOL, RELEASE - TOOL ASSY RESETTING	5120	U1604	4	US\$ 1916.79	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR072001F9	59/2024	MBEU192163	RIGGING LINE STOWAGE HOOK - RIGGING LINE STOWAGE HOOK	4920	U1604	6	US\$ 659.32	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR025001F9	59/2024	MBEU74276	WRENCH,SPANNER - SPANNER PEG	5120	U1604	3	US\$ 1990.56	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR024020F9	59/2024	MBEU59053	SUPPORT BOX (CAIXA DA PRENSA) -	1560	U1604	1	US\$ 23399.85	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR065003F9	59/2024	MBEU59034	TOOL, TOP LOCKS, TORQUE - Spanner	5120	U1604	3	US\$ 1372.06	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR065001F9	59/2024	MBEU54724	PLUG.BLANKING - Blanking Plug	1670	U1604	3	US\$ 122.48	23/04/2024 11:00:00 GMT-3 (-03:00)
LSR071003F9	59/2024	J84323	PACKING ADAPTER - PACKING ADAPTER	1670	U1604	6	US\$ 4132.14	23/04/2024 11:00:00 GMT-3 (-03:00)

LSR071005F9	59/2024	MBEU121231-3	COMBINED CENTRIFUGE 400V THREE PHASE - COMBINED CENTRIFUGE 400V THREE PHASE	1680	U1604	2	US\$ 13459.34	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR074004T1	60/2024	55-14-3003-1	BRUSH,ELECTRICAL CONTACT - PN ALT M5000-1,	5977	54395	30	US\$ 300.45	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073001T1	60/2024	7011F5-160-T	RING SEAL - CJM PN: 312-10806-001	5365	62064	4	US\$ 332.57	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072005T1	60/2024	PWC30127	PULLER,STAGE PLANET - NSN 5120-008379331	5120	75245	2	US\$ 3128.72	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072015T1	60/2024	756-550	PRIORITY VALVE ASSEMBLY -PN CJM: 312-12047-503 , PN ALT 2135-102.	1650	DN004	12	US\$ 688.47	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072010F5	61/2024	RA22756	PARTS KIT,ROTARY PUMP - PARTS KIT,ROTARY PUMP	4320	51663	10	US\$ 3384.01	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR074008F5	61/2024	503117-001	MODULE ASSY, POWER LEVER CONTROL - NSN: 6130-01-345-7385 - We accept IW 508316-001 Power Lever Controller, model 5C36 or model 5C35. If the material is being shipped from the USA, it should be used INCOTERMS 2010 FCA, and delivered at our US warehouse: 4601 Beech Road, Temple Hills, MD 20748 Phone: (301) 423-2515. Payments will be made by BACW to the CONTRACTED PARTY within thirty (30) days of the receipt by the BACW of the contracted service.	6130	54933	2	US\$ 32528.05	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072008F5	61/2024	182838	PACKING,PREFORMED - PACKING,PREFORMED	5330	66503	20	US\$ 1.81	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073009F5	61/2024	RK0183	PARTS KIT,LINEAR ACTUATING CYLINDER ASSEMBLY - I.W. PK8839-4	1650	76823	20	US\$ 99.19	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072016F5	61/2024	NAS1303-29	BOLT,SHEAR - BOLT,SHEAR	5306	80205	10	US\$ 1.23	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR078009F5	61/2024	93767	PARTS KIT,HYDRAULIC PUMP - PARTS KIT,HYDRAULIC PUMP	4320	99207	6	US\$ 5028.19	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072014F5	61/2024	841B72P1	BEARING,ROLLER,CYLINDRICAL - BEARING,ROLLER,CYLINDRICAL	3110	99207	2	US\$ 1238.83	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR072017F5	61/2024	RK0216	PARTS KIT,LINEAR ACTUATING CYLINDER ASSEMBLY - PARTS KIT,LINEAR ACTUATING CYLINDER ASSEMBLY	1650	OJRC1	17	US\$ 204.21	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073012F5	61/2024	RK0271	PARTS KIT,LINEAR ACTUATING CYLINDER ASSEMBLY - I.W. RK0216	1650	OJRC1	10	US\$ 218.79	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073006F5	62/2024	ID86-101-507	PARACHUTE,AIRCRAFT,DECELERATION - WE DON'T ACCEPT PN 6-42300-501.	1670	57172	20	US\$ 14577.00	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR073007GS	63/2024	PWC32449	THERMOCOUPLE, HEATING ELEMENT - NSN 6685-01-617-0596	6685	77445	16	US\$ 3158.71	23/04/2024 11:00:00 GMT-3 (-03:00)
SPR057011F9	64/2024	BERUTOX LF 20	GREASE, POLYTETRAFL - GREASE, POLYTETRAFL	9150	C1613	12	US\$ 189.84	24/04/2024 11:00:00 GMT-3 (-03:00)
PBR050005CP	65/2024	30903933	SQUIB, FIRE EXTINGUISHER - Squib for fire extinguisher, for use on the KC-390 aircraft	1377	05167	1	US\$ 1720.01	25/04/2024 11:00:00 GMT-3 (-03:00)
PBR072001CP	66/2024	30903931	CARTRIDGE FIREX-BOTTLE - Item used on KC-390 aircraft. The term "CARTRIDGE FIREX BOTTLE" refers to the "Fire Extinguishing Bottle Cartridge" and is an important component of the fire extinguishing system used in the KC-390 aircraft, being designed to detect, contain and extinguish fires in different areas critical parts of the aircraft, such as cargo compartments, engine compartments and hydraulic systems. When a fire is detected in a protected area of the aircraft, the item is electrically activated, which causes the release of the extinguishing agent. This agent is released in the form of gas, creating a mist that smothers the fire and prevents its spread. Manufacturing date, service life, shelf-life and technical order number are required.	1377	59734	1	US\$ 1297.88	25/04/2024 11:00:00 GMT-3 (-03:00)
PBR067005CP	67/2024	30903899	CARTRIDGE,AIRCRAFT FIRE EXTINGUISHER - Cartridge for aircraft fire extinguisher, for use on the KC-30 aircraft. Manufacturing date, service life, shelf-life and technical order number are required.	1377	05167	2	US\$ 1345.18	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR071001C1	68/2024	6510-56FT	JACK,AXLE - PN: 6510-56FT: Equipment used in Tire/Wheel and Brake Replacement, for main and nose landing gears of the A330-200 aircraft. Vertical capacity of 65 TON. Data Sheet attached.	1730	00994	3	US\$ 32422.19	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR073001C1	68/2024	14-6806-6011	GAGE,TIRE PRESSURE,SELF-CONTAINED -	4910	59603	5	US\$ 507.62	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071005C1	68/2024	14-6883-0110	TRUCK,LIFT,WHEEL - NSN: 4910015017986 - SPECIFICATIONS: LENGTH IN (CM): 52 (132); WIDTH IN (CM): 33.5 (85); HEIGHT IN (CM): 32 (81); WEIGHT LB (KG): 33 (84).	4910	59603	1	US\$ 6883.57	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071003C1	68/2024	TTL-300-DTI-HA	TIRE INFLATOR,AIRCRAFT,AUTOMATIC - TTL DIGITAL AIRCRAFT TIRE INFLATOR; 0-300 PSI; Range (C): 0-300 PSI ; Accuracy: +/- 0.25% F.S. ; Gauge Size: 3" 1/4 NPT	1560	850B8	5	US\$ 492.36	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071006C1	68/2024	D97800-003	ACTUATOR-MECHANICAL -	1680	F0422	4	US\$ 5617.34	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071002C1	68/2024	98F29203002000	DRAINING TOOL-HYDRAULIC RESERVOIR - NSN: 4820-14-564-6112 ;	4820	FAPE3	2	US\$ 3617.39	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071009C1	68/2024	98F29208457000	PIN-SAFETY,RAT - NSN: 1730145652294	1730	FAPE3	4	US\$ 1990.54	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR072007C1	68/2024	98F24208245003	HOIST-APU GENERATOR -	1680	FAPE3	1	US\$ 7999.10	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR071007C1	68/2024	98A28201003000	FUEL PUMP,SHROUD TOOL -	1680	FAPE3	1	US\$ 916.79	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR072003C1	68/2024	460007011	SPANNER-AXLE NUT,MLG - NSN: 5120998128602	5120	K0654	1	US\$ 740.56	26/04/2024 11:00:00 GMT-3 (-03:00)
GLR025011C5	69/2024		COMPREHENSIVE DIAGNOSTIC AGREEMENT N° 1-1051843 FOR CF34-10E THE VENDOR SHOULD PROVIDE THE FOLLOWING DIAGNOSTIC SERVICE TO SUPPORT THE VC-2 FLEET ENGINES: 1) BASIC SERVICE ELEMENTS 2) REPORTS 3) PROGRAM MANAGEMENT AND SUPPORT FROM MANUFACTURER 4) DATA REVIEW SERVICE RELATES TO ENGINES WITH THE FOLLOWING PNS AND SNS: PN CF34-10E6A1G07 (SN 994751) (SN 994601) (SN 994750) (SN 994603) AND PN CF34-10E6A1G08 (SN 994663)			5	US\$ 4024.52	22/04/2024 11:00:00 GMT-3 (-03:00)
GLQ312017P3	70/2024	DL1326M39-4	ACTUADOR, ELETRO-MECHANICAL - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0094-00 ITEM 73 (The page of which is attached).	1680	12511	1	US\$ 1906.38	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308043P3	70/2024	605600-2-1	FAN, TUBEAXIAL- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-4 F0021-00 ITEM 20 (The page of which is attached).	4140	70210	2	US\$ 32785.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308042P3	70/2024	585500	SYNCHROPHASER- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-8 F0089-00 ITEM 27 (The page of which is attached).	1610	73030	2	US\$ 23141.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ307008P3	70/2024	393007-07870	INDICATOR FUEL QUANTITY - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0050-00 ITEM 13 (The page of which is attached).	6680	89305	1	US\$ 12144.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308059P3	70/2024	391074-02749	TANK UNIT- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0057-00 ITEM 7 (The page of which is attached).	6680	89305	3	US\$ 360.90	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ307003P3	71/2024	B40831-1	VALVE ASSEMBLY,MANIFOLD - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-12 F0002-00 ITEM 7 (The page of which is attached).	4820	04577	1	US\$ 20105.39	29/04/2024 11:00:00 GMT-3 (-03:00)

GLQ308008P3	71/2024	B40831-1	VALVE ASSEMBLY,MANIFOLD- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-12 F0002-00 ITEM 7 (The page of which is attached).	4820	04577	2	US\$ 20105.39	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308063P3	71/2024	43030-11	VALVE, CROSS- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-4 F0032-00 ITEM 9 (The page of which is attached).	4810	19156	12	US\$ 21794.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ307009P3	71/2024	891450-01	CONTAINER ASSY,FIRE- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0024-00 ITEM 39 (The page of which is attached).	1680	61423	2	US\$ 26349.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308107P3	71/2024	891450-01	CONTAINER ASSY,FIRE - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0024-00 ITEM 39 (The page of which is attached).	1680	61423	4	US\$ 32473.24	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308037P3	71/2024	3053570-1-1	VALVE, DIRECTIONAL F - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-2 F0037-00 ITEM 90 (The page of which is attached).	1650	77068	2	US\$ 28319.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ305008P3	71/2024	656-7844-001	WASHER,SEAL - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: E-01-75PAA-4-27, SECTION 51,F04,120 (The page of which is attached).	5310	95105	50	US\$ 119.90	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ305021P3	71/2024	940-0330-001	PROCESSOR,RADAR DAT - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: E-01-75PAA-4-21; SECTION 52; F 04; IND NUMBER 180	5841	97896	2	US\$ 70881.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308032P3	72/2024	28B95-15D-V	GENERATOR,ALTERNATING CURRENT- WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0017-00 ITEM 38 (The page of which is attached).	6115	64547	8	US\$ 65271.00	22/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308017P3	72/2024	R1596M5	ACTUATOR,ELECTRO-MECHANICAL,LINEAR - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0041-00 ITEM 38 (The page of which is attached).	1680	81039	14	US\$ 65731.00	22/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308060P3	72/2024	393007-07869	INDICATOR FUEL QUANTITY - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-5 F0050-00 ITEM 12 (The page of which is attached).	6680	89305	12	US\$ 34896.00	22/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308106P3	73/2024	181880-1-1	HEAT EXCHANGER, AIR TO AIR, AIRCRAFT - WITH FRESH FAA FORM 8130-3 - TECHNICAL ORDER: NAVAIR 01-75PAA-4-4 F0021-00 ITEM 6 (The page of which is attached).	1660	70210	1	US\$ 43300.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLQ308069P3	73/2024	8TJ64GAL	TRANSMITTER,RATE OF FLOW - TECHNICAL ORDER: 01-75PAA-4-5; F075-00; IND N° 10 - DELIVERY WITH FRESH FAA FORM 8130-3	6620	97424	2	US\$ 32994.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR072004C4	74/2024	324843-2020	HEADSET-MICROPHONE - NSN: 5965016554235	5965	32108	24	US\$ 1548.55	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022012C8	75/2024	908900-01-01	CONTROL UNIT, SMOKE DETECTION	6350	25693	1	US\$ 340959.87	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022011C8	75/2024	391-03600-403	BLEED, PYLON, INSTL	2910	001JK	1	US\$ 9997.77	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022022C8	75/2024	390-47779-401	STUD,SHOULDERED ANDSTEPED - NSN 5307-14-366-1956 - NHA: 524-031	1560	001JK	1	US\$ 2817.69	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022021C8	75/2024	390-99810-414	LOGISTIC LOCK ASSY, CARGO RAMP - LOGISTIC LOCK ASSY, CARGO RAMP	1560	001JK	1	US\$ 122037.17	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022023C8	75/2024	892480	EXTINGUISHER, FIRE (H2O)	4210	0KDP7	4	US\$ 11683.48	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022014C8	75/2024	727-1376/01	FLASHLIGHT	6230	A4582	12	US\$ 2577.30	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022024C8	75/2024	P3APP003010A	PORTABLE FIRE EXTINGUISHER, 2-BTP, 3.52 LB - PORTABLE FIRE EXTINGUISHER, 2-BTP, 3.52 LB	4210	CE579	1	US\$ 1643.37	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022019C8	75/2024	6142.2800K92	TRANSCRYPTOR DIGITAL	5821	D0894	1	US\$ 235721.41	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022025C8	75/2024	E38130-01	FIRST AID OXYGEN CYLINDER 11 FT3, A	1660	D1379	2	US\$ 4963.97	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022013C8	75/2024	39-0069	PUMP SUBASSEMBLY,RO	4320	K2523	1	US\$ 60058.21	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022008C8	76/2024	1012-000-912-0	PPSU BOARD	1560	001JK	1	US\$ 67327.06	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022004C8	76/2024	1720141F	CONTROL UNIT, ELECTRONIC, SLAT/FLAP	5999	001JK	2	US\$ 199840.86	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022020C8	76/2024	390-99592-415	LOCK,ADS,LH - LOCK,ADS,LH	1560	001JK	1	US\$ 107522.30	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022007C8	76/2024	100-2680-02-16	BATTERY, BACKUP, LITHIUM, 10AH	6140	OTMJ9	1	US\$ 19419.38	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022003C8	76/2024	114081-301	ARMING VALVE ASSY	1560	6UF58	1	US\$ 19995.00	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022005C8	76/2024	100-A1024-01	CARGO DOOR ACTUATOR	1560	A0809	1	US\$ 69444.46	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022006C8	76/2024	E38912-01	PRESSURE REDUCER VALVE - PRESSURE REDUCER VAL	4820	D1379	1	US\$ 40982.13	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022001C8	76/2024	E21360000	TACHOMETER	6680	F6137	6	US\$ 8046.61	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022010C8	76/2024	3022147-100	PUMP, AC MOTOR DRIVEN, HYDRAULIC, A	1650	K4413	1	US\$ 120938.11	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR022009C8	76/2024	0035C000000-00	CONTROLLER, STEERING CONTROL UNIT	1620	K8081	1	US\$ 131864.86	29/04/2024 11:00:00 GMT-3 (-03:00)
GLR060003C8	77/2024	FDC9839M	RETRIEVAL SPOOL, ADJUSTABLE - - Technical Order: EMBRAER 390EN - AIPC 4962	1560	001JK	1	US\$ 2555.78	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR022026C8	77/2024	A37678	REDUCER - REDUCER	1560	001JK	2	US\$ 600.38	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR060002C8	77/2024	390-03400-906	SEAL LEADING EDGE -	1560	01U4K	1	US\$ 6997.49	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR025004C8	77/2024	Y32014XK0629	CUP, BEARING - CUP, BEARING	1560	F6137	7	US\$ 394.80	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR025003C8	77/2024	A37505	SEAL, INNER BEARING - SEAL, INNER BEARING	3110	F6137	19	US\$ 530.79	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR025001C8	77/2024	A37508-1	BAR, TORQUE - Technical Order: SAFRAN TASK 32-49-33-871-802-A01	5120	F6137	110	US\$ 994.13	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR025002C8	77/2024	A37502	SEAL, INNER BEARING - SEAL, INNER BEARING	3110	F6137	19	US\$ 530.79	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR036001C8	77/2024	C20698101	CARBON BRAKE -	1630	F6137	6	US\$ 92294.97	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR066001C8	77/2024	AESP504	FIRST AID KIT,AIRPL - T.O.: EMBRAER 390EN - AIPC 4962	1680	FB459	3	US\$ 205.84	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR060001C8	77/2024	2139-5100-403	MLG DOOR ACTUATOR, ASSY -	1560	FB459	1	US\$ 44061.81	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR003011F4	78/2024	CTS002	CONECTOR, ELECTRICAL (P7583 P7584) - CONECTOR, ELECTRICAL (P7583 P7584)	5935	66197	4	US\$ 103.42	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR003003C4	79/2024	23065890	CARBON SEAL. FAN - IPC 72-00-21-01, Page 1, Fig 01, Item 20 (The page of which is attached).	5331	63005	2	US\$ 4495.00	01/05/2024 11:00:00 GMT-3 (-03:00)
GLR003005C4	79/2024	23056031	FILTER,FLUID - IPC 73-21-10-01, Page 01, Fig 01, Item 10 (The page of which is attached).	2915	73342	3	US\$ 1774.27	01/05/2024 11:00:00 GMT-3 (-03:00)

ILR082001TI	80/2024	Acquisition of access, billed per student, to online simulator "Littlefield Technologies", a discrete-event Monte Carlo simulator where each team of students is assigned with factory management decisions. The scenario must be a make-to-order manufacturer using a process consisting of four steps on three stations. Orders arrive and are matched to kits in raw materials inventory. Students may select from a set of pre-determined contracts that determine the relation between customer lead time and revenue. Contracts penalize teams when lead times exceed a quoted level. Cage code 5UMH9.				15	US\$ 9.00	24/04/2024 11:00:00 GMT-3 (-03:00)
-------------	---------	--	--	--	--	----	-----------	------------------------------------