

e-RA - Atualizado em: 26/12/2024

Número BAC	Cotação e-RA Número da Peça	Nome do Item	Fabricante	Qty	Valor Máximo Unit.	Fechamento da Fase Inicial de Propostas
ELRR218044R	640/2024	G533947-1	09675 - RAYTHEON CANADA LIMITED	1	US\$ 139,000	Dec 12, 2024, 11:00 AM (-0300)

NOTE: MINIMUM WARRANTY 12 MONTHS.

*** IMPORTANT: YOU MUST INFORM ON THE RFQ'S REMARKS:

- 1) YOUR COMPANY'S FAA OR EASA # OR SIMILAR CERTIFICATE #
- 2) FIXED EVALUATION FEE.
- 3) SERVICE OFFERED WARRANTY.
- 4) FOR EXCHANGE UNITS, YOU MUST INFORM THE SN AND CONDITION OF THE UNIT OFFERED. ***

IMPORTANT: FAILURE TO PROVIDE THE INFORMATION REQUESTED ABOVE MAY RESULT ON YOUR COMPANY'S DECLASSIFICATION FROM THIS RFQ PROCESS. (T&C CHAPTER III - PRICE PROPOSALS 3.12)

ATTENTION: UPON RECEIPT OF THE UNIT BY THE WINNING COMPANY FOR REPAIR/OVERHAUL SERVICE, AN INITIAL ASSESSMENT MUST BE CARRIED OUT AT THE UNIT, AND A TEARDOWN REPORT WITH THE RESULT OF THE EVALUATION, MUST BE PROVIDED WITHIN 15 BUSINESS DAYS. IF THE TEARDOWN REPORT CANNOT BE PROVIDED WITHIN 15 BUSINESS DAYS, THE COMPANY MUST INFORM THE REASON WITHIN 10 WORKING DAYS.

THE TEARDOWN REPORT MUST HAVE:

- 1 - DETAILS ALL SERVICES TO BE EXECUTED ON THE UNIT AND LIST ALL PART NUMBERS NEEDED TO BE REPLACED AND/OR PURCHASED IN ORDER TO REPAIR/OVERHAUL THE UNIT WITH THEIR INDIVIDUAL PRICES.
- 2 - ESTIMATED DELIVERY DATE.
- 3 - SERVICE WARRANTY.
- 4 - FIXE EVALUATION FEE.

ATTENTION: THE SERVICE CAN ONLY BE PERFORMED UPON RECEIVING CABW FINAL WRITTEN APPROVAL.

ATTENTION: UNITS RETURNED WITH SERVICE PERFORMED FOR THE SAME PRICE AS THE PO, AN EMAIL NOTICE MUST BE PROVIDED PRIOR TO THE UNIT SHIPMENT.